

Release Notes

FortiSwitch-AX9000-OS 1.0.0



FORTINET DOCUMENT LIBRARY

<https://docs.fortinet.com>

FORTINET VIDEO LIBRARY

<https://video.fortinet.com>

FORTINET BLOG

<https://blog.fortinet.com>

CUSTOMER SERVICE & SUPPORT

<https://support.fortinet.com>

FORTINET TRAINING & CERTIFICATION PROGRAM

<https://www.fortinet.com/training-certification>

FORTINET TRAINING INSTITUTE

<https://training.fortinet.com>

FORTIGUARD LABS

<https://www.fortiguard.com>

END USER LICENSE AGREEMENT

<https://www.fortinet.com/doc/legal/EULA.pdf>

FEEDBACK

Email: techdoc@fortinet.com



December 3, 2025

FortiSwitch-AX9000-OS 1.0.0 Release Notes

99-100-1199729-20251203

TABLE OF CONTENTS

Change log	4
Introduction	5
Supported hardware	6
Special notices	7
Known issues	8

Change log

Date	Change Description
November 6, 2025	Initial document release for FortiSwitch-AX9000-OS 1.0.0
November 19, 2025	Corrected the documentation link in Introduction on page 5 .
December 3, 2025	Updated the description of bug 1206665.

Introduction

This document provides the following information for FortiSwitch-AX9000-OS 1.0.0 build 0003:

- [Supported hardware on page 6](#)
- [Special notices on page 7](#)
- [Known issues on page 8](#)

See the [Fortinet Document Library](#) for FortiSwitch-AX9000-OS documentation.

Supported hardware

FortiSwitch-AX9000-OS 1.0.0 supports the following hardware:

Model	Description
FS-AX9004G	Layer 2/3 chassis switch for up to four line cards.
FS-AX9000G-SUP	FS-AX9000G-SUP controls the FS-AX9004G chassis and performs packet forwarding.
FS-AX9000G-LC10P	FS-AX9000G-LC10P line card features 48x 10/5/2.5/1 GE RJ45 ports as well as 2x 10GE SFP+ ports. All RJ45 ports support PoE (802.3bt/at/af, up to 90W per port).
FS-AX9000G-LC10S	FS-AX9000G-LC10S line card features 48x 10/1 GE SFP+/SFP ports as well as 2x 10GE SFP+ ports.
FS-AX9000G-LC25	FS-AX9000G-LC25 line card features 48x 25/10 GE SFP28/SFP+ ports as well as 4x 100/40 GE QSFP28/QSFP+ ports.
FS-AX9000G-LC100	FS-AX9000G-LC100 line card features 32x 100/40 GE QSFP28/QSFP+ ports.
FS-AX9004G-FAN	FAN module for FS-AX9004G.
FS-AX9000G-PS-3KAC	AC power supply for FS-AX9000G series.
FS-AX9000G-PS-2K5DC	DC power supply for FS-AX9000G series.

Special notices

Supervisor (FS-AX9000G-SUP) redundancy is not supported in FortiSwitch-AX9000-OS 1.0.0.

The following features are not supported in FortiSwitch-AX9000-OS 1.0.0:

- Commit mode for configuration
- Backing up and restoring operating information
- Advanced script
- VLAN tunneling (QinQ)
- Setting any TPID value feature
- Outbound filters (access lists)
- Policer
- Port mirroring
- Policy-based routing

Known issues

The following known issues have been identified with FortiSwitch-AX9000-OS 1.0.0. For inquiries about a particular bug or to report a bug, please contact [Fortinet Customer Service & Support](#).

Bug ID	Description
1198289	The following MIB object is not supported: <ul style="list-style-type: none">• fsaxFlow
1198289	The following MIB object is not supported: <ul style="list-style-type: none">• fsaxQueue
1198293	The following configuration commands are not supported: <ul style="list-style-type: none">• qos-queue-group• qos-queue-list• traffic-shape rate
1198297	In the access-list configuration for filtering and QoS, the following commands can be configured, but the configuration does not take effect: <ul style="list-style-type: none">• range parameter of tcp port and udp port• neq parameter of tcp port and udp port• layer2 parameter of deny and permit• layer3 parameter of deny and permit• advance access-list resequence• ip access-list resequence• ipv6 access-list resequence• mac access-list resequence
1206660	The following limitations apply when access list logging is configured for protocol control packets addressed to this device. <ul style="list-style-type: none">• It will be excluded from access list logging.• Packets are not discarded even if the filter is specified to be discarded. If you want to discard protocol control packets addressed to this device, do not apply access list logging to the filter.
1206661	The number of allowaccess settings for the entire device is up to 1,000.
1206663	Daylight saving time should be set using the number parameter in the “clock timezone”. Do not use the “clock summer-time” configuration command.
1206665	When using IGMP snooping, configure one or more multicast router ports for VLAN where IGMP snooping is enabled. When using MLD snooping, configure one or more multicast router ports for VLAN where MLD snooping is enabled.

Bug ID	Description
1206665	<p>When the “system flash-monitor configuration command” is set, the following recovery system message is not displayed even if the free space of the internal flash memory falls below the threshold specified in the recovery-threshold parameter:</p> <pre>01221011 The internal flash memory has enough free space.</pre>
1206665	<ul style="list-style-type: none"> • The “show system” operation command and MIB object are set to “1000BASE-T full (auto)” for the speed of the management port, regardless of the configuration. • If multiple LCs are used, the LC power status displayed by “show power” is “-”. • The SUP status is incorrectly displayed as “active” in the “show system” operation command when the system is stopped automatically due to a faulty SUP restarting 7 times within a one-hour period.
1206665	<p>If the device is restarted with the “reload active” operation command or if a SUP failure occurs, the dump file pfmosXX.000 is not output.</p>
1206665	<p>The “system temperature-warning-level” configuration might not take effect when the device starts up. If this occurs, you need to delete and reconfigure the “system temperature-warning-level” configuration.</p>
1206665	<p>The following FAN-related issues occur:</p> <ul style="list-style-type: none"> • When the system is powered on, a false FAN unit failure is detected, causing all three FAN units to run at high speed. • When a FAN unit is replaced, a false failure of the newly installed FAN unit is detected, causing all three FAN units to continue running at high speed. • When a FAN unit is removed, the following system message, which should not normally be generated for the removed FAN unit, is output incorrectly: <pre>S4 FAN FAN:X 01213006 00 ffc0a000000 The fan speed was changed to high.</pre> <p>To recover from these issues, the system must be rebooted using the “reload” command without turning the power off. When the system restarts, all three FAN units initially run at high speed. The FAN units slow down gradually and back to normal speed within approximately 30 to 40 minutes.</p>

Bug ID	Description
1206665	<p>Brief outages of packet forwarding intra VLAN (bridging) and SVI (routing) occur after the following events. In the following description, “affected” means a brief outage on that VLAN (for an average of 35 milliseconds).</p> <ul style="list-style-type: none"> • Configuration changes by operator: <ul style="list-style-type: none"> ◦ VLANs are affected when they are removed from the list of allowed VLANs for the trunk port. ◦ The default VLAN (VLAN 1) is affected when “switchport access vlan <n>” is configured. ◦ When IPv4 direct broadcast forwarding is enabled on an SVI, and upon disabling it, the corresponding VLAN is affected. • Network state changes without the operator’s intervention: <ul style="list-style-type: none"> ◦ VLANs are affected when configured as allowed VLANs on the channel group, and the entire channel group goes up or down. ◦ The VLAN is affected when the corresponding SVI is the IPv4/IPv6 unicast route’s outgoing interface, ARP/NDP for the next hop is removed, and the MAC address for the next hop is not learned. • Network state changes when PIM is configured on FS-AX9004G: <ul style="list-style-type: none"> ◦ The VLAN is affected when a MAC address learned by IGMP/MLD snooping is removed. ◦ The VLAN is affected when a destination port for a MAC address learned by IGMP/MLD snooping is removed. ◦ The VLAN is affected when a multicast router port for a MAC address learned by IGMP/MLD snooping is removed. ◦ The VLAN is affected when the output interface of a IPv4/IPv6 multicast route is removed.
1206667	<p>Flow control on LC100 supports only receiving pause frames. Transmitting pause frames is not supported.</p>
1206667	<p>When using 1000/2.5G/5G/10GBASE-T ports with 2.5GBASE-T or 5GBASE-T, after link-up, the link might go down once before coming up again.</p> <p>Workaround: You need to use the “link up-debounce” configuration command to set the debounce timer when linking up for about 5 seconds. You also need to configure the debounce timer on the peer device side as well.</p>
1206668	<p>Device-originated packets sent to an SVI (VLAN interface) are detected by a filter configured for inbound traffic on the same SVI (VLAN interface).</p> <p>Workaround: This issue can be avoided by applying a filter to the Ethernet interface. If you want to apply a filter to an SVI (VLAN interfaces), you can set the filter to prevent packets transmitted by this device from being discarded by applying the source MAC address and source IP address to the detection conditions.</p>
1206669	<p>In case of VRF extranet communication, the subnet broadcast traffic is incorrectly forwarded, even if there is no directed-broadcast option in the “ip address” configuration.</p>
1206669	<p>In the “show ip arp” and “show ipv6 neighbors” commands, entries with the “I” (Incomplete) status are not displayed.</p>
1206669	<p>If a secondary address is set for a multihomed configuration on the IPv4 interface, the source address of the IPv4 packet sent from this device will be the primary address, even if it is supposed to be the secondary address.</p>

Bug ID	Description
1206669	This device does not send ICMP redirect packets or ICMPv6 redirect packets.
1206669	The uRPF strict mode cannot be used on IPv6 interfaces.
1206669	Even if the “no ip source-route” configuration command is set, the forwarding of IPv4 packets with the source route option might not be suppressed.
1206670	Port-channel subinterfaces cannot be used when they are untagged. You can use them when they are tagged.
1206672	IGMP snooping and IPv4 multicast routing or MLD snooping and IPv6 multicast routing cannot be used at the same time on the same SVI (VLAN interface).
1206673	When using the non-link-down mode on a standby link in link aggregation, the frames received on the standby port are discarded.
1206674	<p>When the MAC address table has a large number of entries, the following settings might not be registered in the hardware:</p> <ul style="list-style-type: none"> • When a static MAC address entry is configured (added or modified) • When the IP address of the SVI (VLAN interface) using “vlan-mac” is configured • When the VRRP virtual IP address is configured <p>When this issue occurs, it results in one of the following system messages:</p> <ul style="list-style-type: none"> • The MAC address in a static entry cannot be registered to the MAC address table. • The IP configuration cannot be registered to the hardware tables. <p>For recovery, you need to delete the MAC address table with the operational command “clear mac-address-table” and then reconfigure the configuration.</p>
1206675	<ul style="list-style-type: none"> • Do not use the “ntp ipv6 multicast” configuration command. • If you are using an access list configured in “ntp access-group”, packets that do not match the access list will be discarded.
1206676	<p>The mixed use of AC and DC power supply units is not supported.</p> <ul style="list-style-type: none"> • AC power supply: FS-AX9000G-PS-3KAC • DC power supply: FS-AX9000G-PS-2K5DC
1206678	VLAN tag translation is not supported on the control VLAN of the Ring Protocol (AXRP).
1206680	<p>The “update software usb-flash-file” operational command does not work.</p> <p>Workaround: Copy the file to the device with the “cp usb-flash-file” operation command in advance and then update the software with the “update software” command.</p>

Bug ID	Description
1206684	<p>The statistics for the following commands and MIBs are fixed to 0.</p> <p>Operation commands:</p> <ul style="list-style-type: none"> • <code>show ip interfaces statistics</code> • <code>show ipv6 interfaces statistics</code> • <code>show ip-dual interfaces statistics</code> • <code>show vlan statistics</code> <p>MIBs:</p> <ul style="list-style-type: none"> • <code>ifTable(VLAN,Subinterface)</code> • <code>ifXTable(VLAN, Subinterface)</code>
1206686	<p>Storm control configurations for the LC10S, LC25, and LC100 ports do not take effect when the device is restarted. After restarting the device, delete the storm control settings and then set them up again.</p>
1206687	<ul style="list-style-type: none"> • When using VRRP with VRF, you cannot use the accept mode on the virtual router (using the configuration command <code>vrrp accept</code>). • If you are using VRRP, do not delete all <code>vrrp ip</code> or <code>vrrp ipv6</code> commands. If you want to delete all <code>vrrp ip</code> or <code>vrrp ipv6</code> commands, delete all VRRP configurations, save the configuration, and then restart the device. • When an interface using VRRP detects duplicate IP addresses, the following system message is produced, but the VRF ID contained in the message is fixed to 0: <code>00400100 S5 Duplication of IPv4 address with the node was detected.</code>
1206688	<p>The following line card installation operations are not allowed while the system is running. In both cases, you need to power down the chassis, replace or insert the line card, and then power up the chassis.</p> <ul style="list-style-type: none"> • Changing an installed line card to a different type in the same slot • Installing LC10S, LC25, or LC100 to the empty slots <p>In addition, if there are port configurations in the form of <code>Interface ethernet <System No.>/<LC No.>/<Port No.></code> that do not exist on the line card you are using, you need to delete them.</p> <ul style="list-style-type: none"> • For LC10P and LC10S, delete ports 51-52 if they exist. • For LC100, delete ports 33-52 if they exist.
1206690	<p>When there are frames with two or more VLAN tags, the frames with the first VLAN ID set to 0 are not discarded.</p> <p>If the second VLAN ID is configured, forward it; if the second VLAN ID is not configured, discard it.</p>
1206691	<p>IPv4 unicast and IPv6 unicast routing table entries cannot be registered up to the capacity limit described in the <i>Administration Guide</i> Volume 1. The total number of entries for IPv4 unicast and IPv6 unicast is limited to 130K.</p> <p>In addition, the configuration command <code>forwarding-table allocation</code> supports only the default value.</p> <p>Specifying the following parameters is not applied to the system:</p> <ul style="list-style-type: none"> • <code>l3-route</code> parameter of the forwarding-table allocation • <code>access</code> parameter of the forwarding-table allocation
1206693	<p>Do not use the <code>no system-source-address</code> configuration command on the loopback interface.</p>

Bug ID	Description
1206694	The following SNMP notifications related to the layer-2 loop detection feature are always sent to the SNMP manager, regardless of the “snmp-server notify-filter” configuration command: <ul style="list-style-type: none">• fsaxL2ldLinkDown• fsaxL2ldLinkUp• fsaxL2ldLoopDetection
1206694	When you get the IfIndex MIB object of the primary loopback interface, it responds with an invalid value. The correct value: <loopback number>+20000 The invalid value: <vrf id>+20000 (“<vrf id>” is the VRF to which the loopback interface belongs.)
1206694	If you get the MIB information of the management port that does not have an IP address, the ifIndex value of the management port is an invalid value. If you want to use the management port, you need to set the IP address.
1206694	The following MIB information cannot be retrieved successfully or responds with incorrect values: <ul style="list-style-type: none">• fsaxModelType• fsaxSoftware• fsaxSystemAlarmTable• fsaxFanUnitTable• fsaxFanUnitLedStatus• Part of fsaxSupBoardTable• Part of fsaxSupCpuTable
1206695	<ul style="list-style-type: none">• Policy-based mirroring cannot be used for traffic on VLANs with the Spanning Tree or Ring Protocol enabled.• Policy-based mirroring cannot be used when the default VLAN (VLAN 1) is shut down.



www.fortinet.com

Copyright© yyyy Fortinet, Inc. All rights reserved. Fortinet®, FortiGate®, FortiCare® and FortiGuard®, and certain other marks are registered trademarks of Fortinet, Inc., and other Fortinet names herein may also be registered and/or common law trademarks of Fortinet. All other product or company names may be trademarks of their respective owners. Performance and other metrics contained herein were attained in internal lab tests under ideal conditions, and actual performance and other results may vary. Network variables, different network environments and other conditions may affect performance results. Nothing herein represents any binding commitment by Fortinet, and Fortinet disclaims all warranties, whether express or implied, except to the extent Fortinet enters a binding written contract, signed by Fortinet's Chief Legal Officer, with a purchaser that expressly warrants that the identified product will perform according to certain expressly-identified performance metrics and, in such event, only the specific performance metrics expressly identified in such binding written contract shall be binding on Fortinet. For absolute clarity, any such warranty will be limited to performance in the same ideal conditions as in Fortinet's internal lab tests. Fortinet disclaims in full any covenants, representations, and guarantees pursuant hereto, whether express or implied. Fortinet reserves the right to change, modify, transfer, or otherwise revise this publication without notice, and the most current version of the publication shall be applicable.