


Release Notes

FortiFone FON-x80 Series 3.0.11



FORTINET DOCUMENT LIBRARY

https://docs.fortinet.com

FORTINET VIDEO GUIDE

https://video.fortinet.com

FORTINET BLOG

https://blog.fortinet.com

CUSTOMER SERVICE & SUPPORT

https://support.fortinet.com

FORTINET TRAINING & CERTIFICATION PROGRAM

https://www.fortinet.com/training-certification

NSE INSTITUTE

https://training.fortinet.com

FORTIGUARD CENTER

https://www.fortiguard.com

END USER LICENSE AGREEMENT

https://www.fortinet.com/doc/legal/EULA.pdf

FEEDBACK

Email: techdoc@fortinet.com



December 17, 2021 FortiFone FON-x80 Series 3.0.11 Release Notes 26-3011-768330-20211217

TABLE OF CONTENTS

Change log	4
Introduction	5
Supported platforms	6
System requirements	
Upgrade information	
What's new	
Resolved issues	10

Change log

Date	Change description
2021-12-17	Initial release of the FortiFone FON-x80 Series 3.0.11 Release Notes.

Introduction

This document provides a summary of support information, upgrade instructions, and resolution of known issues in this FortiFone FON-x80 Series version 3.0.11, build 201.

Supported platforms

FortiFone version 3.0.11, build 201 supports the following FortiFone IP phone models:

- FON-380
- FON-480

System requirements

The FortiFone FON-x80 Series version 3.0.11 requires the FortiVoice phone system version 6.0.7, 6.4.1 or later.		

Upgrade information

To upgrade to FortiFone FON-x80 Series version 3.0.11, perform the following procedures:

Download the firmware image file

- 1. Go to the Fortinet Customer Service and Support website.
- 2. Log in to your existing account or register for an account.
- 3. Select Support > Firmware Download.
- 4. In Select Product, select FortiFone.
- 5. Click the Download tab.
- 6. Locate the firmware image file that you need to download.
- 7. To download the image file, go to the end of the row and click HTTPS.
- 8. Select to save the file and click OK.
- 9. Take note of the location where you saved the firmware image file on your computer.

Upgrade the FortiFone firmware

For details about upgrading the FortiFone firmware, see the Managed system > FortiFone firmware upgrades section in the FortiVoice Cookbook, for the applicable FortiVoice phone system version.

What's new

FortiFone FON-x80 Series version 3.0.11 build 201 includes the following improvements and new features:

- Visual voicemail enhancements
- Emergency paging support for multicast group

Resolved issues

The following issues have been fixed in FortiFone FON-x80 Series version 3.0.11 build 201. For inquires about a particular bug, contact Fortinet Customer Service and Support.

Bug ID	Description
764523	In the case of a failover, the FON-x80 phone does not try to reach the second proxy before moving to the backup site.
764313	When a call is switched to an emergency page and the ongoing call is disconnected, the FON-x80 phone can make an intermittent loud tone burst.
745050	The FON-380 phone is not connecting to the VLAN.
750927	Updated programmable keys for FortiVoice Cloud.
764940	When the FON-x80 phone has Mute enabled while on a call and then the user declines an incoming call, the Mute status automatically changes to disabled.
763227	Enhancement required to avoid the screen burn-in behavior when the screen saver is disabled.
763332	The FON-x80 phone stops subscribing to DND status updates and notifications for line, extension, and park appearances.
761245	The FON-x80 phone plays an incorrect ring pattern.
746379	Turning a ringer off by using the Menu settings does not show the ringer-off icon.
758113	When entering DTMF digits during a call, the final character remains visible indefinitely.
742886	Pop-up messages interfere with dialing digits.
747275	When adding a personal contact, an indication says the main number is required.
749291	Improvements required to the FON-X80 traffic capture page branding and layout
751388	FON-x80 phones ignore the label truncation mode setting.
751196	The displayed software version is truncated in Status > General > Software version.
751830	Ping and traceroute functions fail in the release build.
743555	FON-x80 phones indicate that the configuration update has failed when it actually has succeeded.
752440	Pressing on the headset button when a Bluetooth headset is paired and connected does not answer the call.
737738	Unable to resolve the FQDN after upgrading a FON-480 phone from firmware 3.0.6 to 3.0.9.
753127	User-defined background images are not allowed on the phone.
745434	Add a timeout period to automatically remove notification messages.
753988	When the user ignores a call by pressing the <i>Ignore</i> button twice, the ring pattern reverts to the default setting.

Bug ID	Description
754430	When configuring a provisioning server IP address (in Setting > Provisioning), pressing the asterisk "*" key should display a period "." instead.
751555	Web portal fixes include removing an unused web page, adding the Logout function, and fixing the Remember me function when logging in.
760938	Special characters like @ and & do not display in a text message.
765160	The traffic capture web page shows an error message (500 Internal Server Error).
767553	A supervised transfer does not complete when the user hangs up the handset.



modify, transfer, or otherwise revise this publication without notice, and the most current version of the publication shall be applicable.