Release Notes

FortiFone FON-x80 Series 3.0.14

F*C***RTINET**®

TABLE OF CONTENTS

Change log

Date	Change description
2022-09-09	Initial release of the FortiFone FON-x80 Series 3.0.14 Release Notes.

Introduction

This document provides a summary of support information, upgrade instructions, and resolution of known issues in this FortiFone FON-x80 Series version 3.0.14, build 237.

Supported platforms

FortiFone version 3.0.14, build 237 supports the following FortiFone IP phone models:

- FON-380
- FON-480
- FON-580

System requirements

The FortiFone FON-x80 Series version 3.0.14 build 237 requires the FortiVoice phone system version 6.0.7, 6.4.1, or later.

Upgrade information

To upgrade to FortiFone FON-x80 Series version 3.0.14, perform the following procedures:

Download the firmware image file

1. Go to the Fortinet Customer Service and Support website.
2. Log in to your existing account or register for an account.
3. Select **Support > Firmware Download**.
4. In **Select Product**, select **FortiFone**.
5. Click the **Download** tab.
6. Locate the firmware image file that you need to download.
7. To download the image file, go to the end of the row and click **HTTPS**.
8. Select to save the file and click **OK**.
9. Take note of the location where you saved the firmware image file on your computer.

Upgrade the FortiFone firmware

For details about upgrading the FortiFone firmware, see the Managed system, FortiFone firmware upgrades section in the FortiVoice Cookbook, for the applicable FortiVoice phone system version.

What's new

FortiFone FON-x80 Series version 3.0.14 build 237 includes the following new feature:

- Allow users to change the default font color (*Menu > Feature > Font Color*). The font color choices are black, white, and gray. To apply the new font color setting, the phone reboots.

Resolved issues

The following issues have been fixed in FortiFone FON-x80 Series version 3.0.14 build 237. For inquiries about a particular bug, contact Fortinet Customer Service and Support.

Bug ID	Description
801153	Fixed some memory leak issues.
809858, 813671, 821441, 829103, 829442	Intermittent phone freeze during various operational states such as boot, idle, and factory reset.
820599	The phone does not perform a graceful SIP de-registration prior to a reboot or factory reset operation.
828328	Using line keys to hold and resume between multiple calls causes the phone to crash.
828562	Network or phone configuration updates cause phone to crash.
831288	The FON-380 phone GUI does not give an indication to the user that the Bluetooth dongle is not present.

FIERTINET.

www.fortinet.com