



FortiSwitch ATCA - Release Notes

VERSION 5.2.4

FORTINET DOCUMENT LIBRARY

<http://docs.fortinet.com>

FORTINET VIDEO GUIDE

<http://video.fortinet.com>

FORTINET BLOG

<https://blog.fortinet.com>

CUSTOMER SERVICE & SUPPORT

<https://support.fortinet.com>

FORTIGATE COOKBOOK

<http://cookbook.fortinet.com>

FORTINET TRAINING SERVICES

<http://www.fortinet.com/training>

FORTIGUARD CENTER

<http://www.fortiguard.com>

END USER LICENSE AGREEMENT

<http://www.fortinet.com/doc/legal/EULA.pdf>

FEEDBACK

Email: techdocs@fortinet.com



May 31, 2016

FortiSwitch ATCA 5.2.4 Release Notes

11-524-372634-20160531

TABLE OF CONTENTS

Change Log	4
Introduction	5
Supported models.....	5
What's new in 5.2.4.....	5
Special Notices	6
General.....	6
FG-5001D operating in FortiController or Dual FortiController mode.....	6
Upgrade Information	7
Upgrading from FortiSwitch ATCA 5.2.0.....	7
Upgrading from FortiSwitch ATCA 5.0.5 or earlier.....	7
Upgrading from FortiSwitch ATCA 5.0.6 or later.....	7
Downgrading to previous firmware versions.....	7
Firmware image checksums.....	7
Product Integration and Support	8
FortiSwitch ATCA 5.2.4 support.....	8
Resolved Issues	9
Known Issues	10

Change Log

Date	Change Description
2016-05-31	Initial release.

Introduction

This document provides the following information for FortiSwitch ATCA 5.2.4 build 0169:

- Supported models
- Special Notices
- Upgrade Information
- Product Integration and Support
- Resolved Issues
- Known Issues

See the [Fortinet Document Library](#) for FortiSwitch ATCA documentation.

Supported models

FortiSwitch ATCA 5.2.4 supports the following models:

FortiController	FTCL-5103B, FTCL-5903C, FTCL-5913C
------------------------	------------------------------------

What's new in 5.2.4

The following is a list of enhancements in 5.2.4:

- Display SLBC `force-to` status in the GUI.

Special Notices

General

The TFTP boot process erases all current switch configuration and replaces it with the factory default settings.

FG-5001D operating in FortiController or Dual FortiController mode

When upgrading a FG-5001D operating in FortiController or dual FortiController mode from 5.0.9 to FortiOS 5.2.2 and later, you may experience a back-plane interface connection issue. After the upgrade, you will need to perform a factory reset and then re-configure the device.

Upgrade Information

Upgrading from FortiSwitch ATCA 5.2.0

FortiSwitch ATCA 5.2.4 supports upgrade from 5.2.0 and above.

Upgrading from FortiSwitch ATCA 5.0.5 or earlier

FortiController units running 5.0.5 or earlier must upgrade to 5.0.6 or later prior to upgrading 5.2.4 in order to receive a necessary update to the FPGA firmware.

Upgrading from FortiSwitch ATCA 5.0.6 or later

FortiSwitch ATCA 5.2.4 introduces an enhanced heartbeat packet that contains more information since the 5.2.0 release. As a result, users must upgrade their FortiGate blades to FortiOS 5.0.10 (or later) or 5.2.2 (or later) before upgrading their FortiController units from FortiSwitch-ATCA 5.0.6 (or later) to 5.2.4.

Downgrading to previous firmware versions

Downgrading from FortiSwitch ATCA 5.2.4 to previous releases is not supported.

Firmware image checksums

The MD5 checksums for all Fortinet software and firmware releases are available at the Customer Service & Support portal, <https://support.fortinet.com>. After logging in select *Download > Firmware Image Checksums*, enter the image file name including the extension, and select *Get Checksum Code*.

Product Integration and Support

FortiSwitch ATCA 5.2.4 support

The following table lists 5.2.4 product integration and support information.

Web browser	<ul style="list-style-type: none">• Microsoft Internet Explorer version 10• Mozilla Firefox version 33• Google Chrome version 37 <p>Other web browsers may function correctly, but are not supported by Fortinet.</p>
FortiOS	<ul style="list-style-type: none">• 5.4.0 and later• 5.2.2 and later• 5.0.9 and later

Resolved Issues

The following issues have been fixed in 5.2.4. For inquiries about a particular bug, please contact [Customer Service & Support](#).

Bug ID	Description
272047	Link-up detection does not work on B1/B2.
308509	Clear <code>force-slave-state</code> flag automatically after FGT graceful upgrade.
308657	Enable GTP-C load-balance in the GUI and CLI.
365132	<code>fabric-mgmt-0</code> and <code>base-mgmt-0</code> interfaces are seen in SNMP polling on FCTL-5103B.
370667	<code>admin-server-cert</code> only takes effect when <code>strong-crypto</code> is enabled.

Known Issues

The following issues have been identified with 5.2.4. For inquiries about a particular bug or to report a bug, please contact [Fortinet Customer Service & Support](#).

Bug ID	Description
368856	Master controller swaps to slave when you create a fabric-channel trunk interface via <code>base-mgmt-external-ip</code> .



Copyright© 2016 Fortinet, Inc. All rights reserved. Fortinet®, FortiGate®, FortiCare® and FortiGuard®, and certain other marks are registered trademarks of Fortinet, Inc., in the U.S. and other jurisdictions, and other Fortinet names herein may also be registered and/or common law trademarks of Fortinet. All other product or company names may be trademarks of their respective owners. Performance and other metrics contained herein were attained in internal lab tests under ideal conditions, and actual performance and other results may vary. Network variables, different network environments and other conditions may affect performance results. Nothing herein represents any binding commitment by Fortinet, and Fortinet disclaims all warranties, whether express or implied, except to the extent Fortinet enters a binding written contract, signed by Fortinet's General Counsel, with a purchaser that expressly warrants that the identified product will perform according to certain expressly-identified performance metrics and, in such event, only the specific performance metrics expressly identified in such binding written contract shall be binding on Fortinet. For absolute clarity, any such warranty will be limited to performance in the same ideal conditions as in Fortinet's internal lab tests. In no event does Fortinet make any commitment related to future deliverables, features or development, and circumstances may change such that any forward-looking statements herein are not accurate. Fortinet disclaims in full any covenants, representations, and guarantees pursuant hereto, whether express or implied. Fortinet reserves the right to change, modify, transfer, or otherwise revise this publication without notice, and the most current version of the publication shall be applicable.