



# AscenLink LinkOS V7.2.23 B7973

Release Notes



AscenLink Release Notes – LinkOS V7.2.23 B7973

February 27, 2018

Revision 1

Copyright© 2018 Fortinet, Inc. All rights reserved. Fortinet®, FortiGate®, and FortiGuard® are registered trademarks of Fortinet, Inc., and other Fortinet names herein may also be trademarks of Fortinet. All other product or company names may be trademarks of their respective owners. Performance metrics contained herein were attained in internal lab tests under ideal conditions, and performance may vary. Network variables, different network environments and other conditions may affect performance results. Nothing herein represents any binding commitment by Fortinet, and Fortinet disclaims all warranties, whether express or implied, except to the extent Fortinet enters a binding written contract, signed by Fortinet's General Counsel, with a purchaser that expressly warrants that the identified product will perform according to the performance metrics herein. For absolute clarity, any such warranty will be limited to performance in the same ideal conditions as in Fortinet's internal lab tests. Fortinet disclaims in full any guarantees. Fortinet reserves the right to change, modify, transfer, or otherwise revise this publication without notice, and the most current version of the publication shall be applicable.

Technical Documentation

<http://help.fortinet.com>

Knowledge Base

<http://kb.fortinet.com>

Forums

<https://support.fortinet.com/forums>

Customer Service & Support

<https://support.fortinet.com>

Training

<http://training.fortinet.com>

License Agreement

<http://www.fortinet.com/doc/legal/EULA.pdf>

Document Feedback

Email: [ascenlink@fortinet.com](mailto:ascenlink@fortinet.com)

# Table of Contents

<b>Introduction</b> .....	<b>1</b>
Summary.....	1
Supported Models .....	1
Compatibility.....	1
<b>Resolved Issues in V7.2.23 B7973</b> .....	<b>2</b>
Mantis ID 468158 .....	2
Common Vulnerabilities and Exposures .....	2
<b>Firmware Upgrade Procedures</b> .....	<b>3</b>
Upgrading Information.....	3
Upgrade procedure .....	3
<b>Getting Help</b> .....	<b>4</b>

# Introduction

## Summary

This LinkOS firmware V7.2.23 B7973 is the twenty-fourth build for Fortinet AscenLink V7.2. In this release, BIND is upgraded to 9.10.6-P1 and a bug about configuration of lots of FQDN is fixed. This document provides a list of resolved issues, upgrade procedures and support information for AscenLink LinkOS V7.2.23 B7973. Please review all sections of this document prior to upgrading your device.

## Supported Models

LinkOS **V7.2.23 B7973** is the latest AscenLink firmware version released for AscenLink-700, AscenLink-5000 and AscenLink-6000.

## Compatibility

LinkOS **V7.2.23 B7973** provides support and is compatible with all versions of LinkReport. AscenLink-6000 requires LinkOS V6.1, or higher.

# Resolved Issues in V7.2.23 B7973

## Mantis ID 468158

When there were more than 400 FQDNs used by AscenLink's service policies (the Source or Destination fields of policies), browsing page Statistics > FQDN would cause system reboot abnormally.

## Common Vulnerabilities and Exposures

AscenLink 7.2.23 is no longer vulnerable to the following CVE-References:

CVE-2017-3145

# Firmware Upgrade Procedures

## Upgrading Information

- Note that only versions later than V6.5 B4175 (V6.5 B4175 is included) are supported for upgrade to V7.2.23 B7973. To upgrade to V7.2 from V6.5 or V7.0, it requires an upgrade of V7.1 first (See “AscenLink V7.1 Firmware Upgrade Quick Guide”, which is available from FortiCare at <https://support.fortinet.com>). For V7.0 (B5338 and B5246), please update to V7.0 B5526 **first** before updating to V7.2.23 B7973.
- System with demonstration licenses cannot be upgraded to R7.1 and later. Please contact Fortinet at [ascenlink@fortinet.com](mailto:ascenlink@fortinet.com) for information on updating these systems to NFR units.
- AscenLink’s firmware image and upgrade license key are available from FortiCare at <https://support.fortinet.com> once customer’s AscenLink Serial Number is registered. However, because of US Government export restrictions on Tunnel Routing technology, all registration to FortiCare for customers using V7.0 or V6.5 **MUST** be "ordered" via your distributor and Fortinet Order Management. Registrations for in-warranty systems will be at no charge, as usual, but Fortinet must have end-user visibility and update its databases in order to support AscenLink. The SKU for ordering a Registration is **AL-REGI-FC**. This is a one-time requirement. Future upgrades will be automatically available to in-warranty customers via the FortiCare website, without the need for additional ordering.

## Upgrade procedure

### Upgrade from V6.5, V7.0 B5526, V7.1 or V7.2.x

After registering to FortiCare, the License Key can be generated inside FortiCare (for in-warranty Serial Number).

Start the upgrade procedure as follow:

- **Always back up your system configurations and store in a safe place before upgrading (and downgrade).**
- Log on to AscenLink as Administrator and go to [System > Administrator] page.
- Click Update to start the upgrade procedure
  - Click Browse to select the path where the new firmware image is saved
  - Enter the Update Key you received from Fortinet
  - Select Upload.
- Be patient while firmware is being upgraded. During the upgrade, do not turn off the system, unplug the power or repeatedly click the Submit button.
- The message “Update succeeded” will appear after the upgrade is completed. Please reboot the system afterwards for the firmware to take effect.

# Getting Help

For customer support of Fortinet's AscenLink products shipped, please contact your local Fortinet AscenLink channel partner or [http://www.fortinet.com/support/contact\\_support.html](http://www.fortinet.com/support/contact_support.html). AscenLink system must be registered to FortiCare to receive support.

Patches and updates are regularly released for Fortinet's AscenLink products. For access, please register at <https://support.fortinet.com/> or contact [ascenlink@fortinet.com](mailto:ascenlink@fortinet.com).

